



Republic of Serbia

**MINISTRY OF FINANCE**

**Department for Contracting and Financing of EU Funded Programmes (CFCU)**

Belgrade, March 2023

**CONTRACTING AUTHORITY'S CLARIFICATIONS no.1**

**Supply of equipment for communicable disease surveillance and for emergency situations**

**Publication ref: NEAR/BEG/2022/EA-OP/0219**

No.	Question	Answer
1	Lot 1, Item No 41 CENTRIFUGE WITH COOLING: Description of Angle rotor in technical specification is not clear (Angle rotor 12x15ml, Angle: 32°, Angle: 45°), only one angle should be specified – please check and clarify.	<i>This issue will be remedied by means of corrigendum no.1 to Tender Dossier.</i>
2	Lot 1, Item No 45 LABORATORY REFRIGERATOR: Gross volume given in technical specification does not match with specified equipment – please check and clarify.	<i>This issue will be remedied by means of corrigendum no.1 to Tender Dossier.</i>
3	Lot 1, Item No 52 THERMOSTAT DRY BLOCK SYSTEM WITH HEATING AND COOLING: Technical specification for this item does not completely correspond to available device – please check and clarify.	<i>This issue will be remedied by means of corrigendum no.1 to Tender Dossier.</i>
4	Lot 1, Item No 22 ULTRA LOW FREEZER (minus 40 to minus 90°C) upright, volume 700-800 L: Description of trays for specified equipment is not clear (-With trays 2 inch 24 x SDR-624-P 6x4 576 139.45 565.4 339.59 134 137 54,5). Please clarify.	<i>This issue will be remedied by means of corrigendum no.1 to Tender Dossier.</i>

**Contracting Authority's clarifications no.1**

<b>No.</b>	<b>Question</b>	<b>Answer</b>
<b>5</b>	Lot 1, Item No 23 ULTRA LOW FREEZER (minus 86°C) upright, volume 50 L: Description of outer cabinet material (Stainless steel) does not match with specified equipment – please check and clarify.	<i>This issue will be remedied by means of corrigendum no.1 to Tender Dossier.</i>
<b>6</b>	Lot 1, Item No 34 ULTRASONIC BATH: External dimensions of specified equipment do not match internal dimensions– please check and clarify.	<i>This is a technical omission. This issue will be remedied by means of corrigendum no.1 to Tender Dossier.</i>
<b>7</b>	Lot 1, Item No 19 FLUOROMETER: Volume of sample given (1ml) in technical specification for this item does not correspond to specification of available equipment - please check and clarify.	<i>This is a technical omission. Volume of sample should be 1 µl (microliter)  This issue will be remedied by means of corrigendum no.1 to Tender Dossier.</i>